



Spare parts drawing - list


Modelnumber: SW1E347101

EU / 20V - "BRUSHLESS MOTOR" Cordless reciprocating saw

SKIL
SW1E347101

Stand }
Issue } 24-02-27

Fig. /Abb. 1



Änderungen vorbehalten
Modifications reserved
Modifications réservées
Salvo modificaciones

Pos.	Spare part number	Description	QTY
1	2851491001	Supporting foot Parts Set	1
2	3135684001	Rubber	1
3	2851492001	Gear Housing & Blade Holder Parts Set	1
4	2751667001	Armature 20V	1
5	2740637002	Field 20V	1
6	2832114001	Switch Parts Set	1
7	3130331001	Button	1
8	2851493001	Housing Parts Set	1
9A	BR1E310701	Battery 20V MAX 2,0Ah (Keepcool) Li-ion	1
9B	BR1E313001	Battery 20V MAX 2,0Ah (Keepcool) Li-ion with USB	1
9C	BR1E310201	Battery 20V MAX 2,5Ah (Keepcool) Li-ion	1
9D	BR1E310401	Battery 20V MAX 4,0Ah (Keepcool) Li-ion	1
9E	BR1E310501	Battery 20V MAX 5,0Ah (Keepcool) Li-ion	1
10A	CR1E312901	Charger EU 230V/20V 1,0A	1
10B	CR1E312201	Charger EU 230V/20V 2,4A	1

10C	CR1E312801	Dual charger EU 230V/20V 2x2,4A	1
10D	CR1E312301	Charger EU 230V/20V 6,0A	1
10E	CR1E313201	Dual charger EU 230V/20V 2x6,0A	1
10F	CR1U312203	Charger UK 230V/20V 2,4A	1
10G	CR1U312803	Dual charger UK 230V/20V 2x2,4A	1
10H	CR1U312303	Charger UK 230V/20V 6,0A	1